

GE Nagrota  
Pin - 901208  
C/o 56 APO

200/Gen/KV/68/BR-II

20 Jul 2021

Principal  
Kendriya Vidyalaya  
Nagrota (J&K)  
Pin-181221

**SAFETY CERTIFICATE OF SCHOOL BLDG AND STAFF QUARTERS  
AND BOUNDARY WALL IN RESPECT OF KV NAGROTA**

1. It is intimated that following buildings were visually inspected and found safe and sound structurally:-

SI No.	Bldg No.	Remarks
(a)	TS-462	Safe on visual inspection
(b)	TS-463	Safe on visual inspection
(c)	TS-464	Safe on visual inspection
(d)	TS-465	Safe on visual inspection
(e)	TS-466	Safe on visual inspection
(f)	TS-467	Safe on visual inspection
(g)	TS-468	Safe on visual inspection
(h)	TS-469	Safe on visual inspection
(j)	TS-470	Safe on visual inspection
(k)	Girls Toilet	Safe on visual inspection
(l)	Boys Toilet	Safe on visual inspection
(m)	Ladies Toilet	Safe on visual inspection
(n)	Gents Toilet	Safe on visual inspection
(o)	Boundary Wall	Safe on visual inspection

2. This is for your info pl.

  
(Sunil R Kabade)  
EE  
Garrison Engineer

**Copy to :-**

E-2 Section